

Date: Friday, 5/25/2007 8:26:03 AM
 User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : BUSHING
Job Number : 32621	
Estimate Number : 10725	
P.O. Number : <i>N/A</i>	Part Number : D2652
This Issue : 5/25/2007 S.O. No. : <i>N/A</i>	Drawing Number : D2652 REV A
Prsht Rev. : NC	Project Number : N/A
First Issue : <i>N/A</i> Type : MACHINED PARTS	Drawing Revision : A
Previous Run : 32467	Material : <i>N/A</i>
Written By : <i>[Signature]</i>	Due Date : 6/10/2007
Checked & Approved By : <i>[Signature]</i> 07.05.28	Qty: <i>217</i> Um: Each
Comment : Est Rev B 02.06.13 Now machined in house. NG	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	M303R0500	303 Round Bar 0.500"
-----	-----------	----------------------



Comment: Qty.: 0.0578 f(s)/Unit Total : 11.5500 f(s)

Material: 303 ss .500" Round Bar

(M303R0500)

Batch: *1102447**101926 4.75'**104919 12' 3 1/2'**(1242)**J.F. 07/07/05*

2.0	HARDINGE	HARDINGE CNC LATHE SMALL
-----	----------	--------------------------



Comment: HARDINGE CNC LATHE SMALL

1-Turn as per Folio FA250 & Dwg D2652

2-Deburr

J.F. 07/07/05

3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

*J.F. 07/07/05**(217)*

4.0	QC8	SECOND CHECK
-----	-----	--------------



Comment: SECOND CHECK

*J.F.**07/07/06**(217)*

5.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: *[Signature]**J.F. 07/07/06 (217)*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: D Date: 07/10/10
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Friday, 5/25/2007 8:26:03 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BUSHING

Job Number: 32621

Part Number: D2652

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



217

Comment: FINAL INSPECTION/W/O RELEASE

Do not release

Job Completion



07/07/10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>[Signature]</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE USA, INC. FAIRCHILD INTERNATIONAL AIRPORT, WA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2652	REV. A SHEET 1 OF 1
DATE 97:03:25		TITLE BUSHING	SCALE 1:1

RELEASED
97/04/25 DS



MATERIAL: AISI 303 SS

NOTE: BREAK ALL SHARP CORNERS 0.010 MAX

TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 32621